



60 Port Boulevard Suite 201 Libby, MT 59923 tel: 406-293-8595 fax: 406-293-8901

January 9, 2007

Ms. Courtney Zamora U.S. Department of Transportation John A. Volpe National Transportation Systems Center 55 Broadway, DTS-4E Cambridge, Massachusetts 02142

Subject:

Libby, Montana Asbestos Project

Property Information for Mel and Lerah Parker

Former Screening Plant, 5000 Highway 37 N, Libby, Montana

Dear Ms. Zamora:

As requested by Volpe, CDM has gathered the removal and restoration documentation for Mel and Lerah Parker's property located at 5000 Highway 37 N in Libby, Montana. Enclosed please find one copy of the following binders for your records:

- Property Information for Parker Property, Former Screening Plant, 5000 Highway 37 N, Libby, Montana; Binder 1 of 2
- Property Information for Parker Property, Former Screening Plant 5000 Highway 37 N, Libby, Montana; Binder 2 of 2

A detailed Table of Contents is provided with each binder.

Two copies of each binder were hand delivered to the EPA Information Center in Libby, Montana for distribution to the EPA and Mel and Lerah Parker. Please feel free to contact me at 720-264-1116 with any questions or comments.

Very truly yours,

Paul Lammers

CDM Libby Site Manager

CDM Federal Programs Corporation

cc: Jeff Montera, CDM - Denver

Contents

BINDER 1		
United States Envi	ironmental Protection Agency	
Libby Asbestos Su		
•	nents as of 16-Oct-2006	
Special Collection	18070	
-	mber 2006	CD 1-14
Libby, Montana A	sbestos Project	
Property Informat:	•	
Mel and Lerah Par		
Former Screening	Plant	
5000 Highway 37 N	V	
CD 1 - Pho	otos	
199	99	
200	00	
200	01	
200)2	
200	03	
Sca	nned 35 mm photos	
Rai	iny Creek Photos 2000 - 2002	
CD 2 - Pho	itos	
200	04	
200	05	
CD 3 - Pho	tos	
200	06	
CD 4 - Scar	nned Documents from:	
Pro	perty Appraisal	
Arc	chaeological Survey	
Con	rrespondence between EPA, Volpe, CDM, and Park	ers
Fill	Material Information	
Inv	restigation Information	
No	tes and Emails from EPA, Volpe, and CDM	
Rip	Rap Information	
San	nple Results	
Sett	tlement Information	
Stip	pend Information	
Wo	orkplans	



CD 5 - Scanned Documents from:

Logbooks

Property Completion Checklists

Removal Information

Restoration Information

Septic System

Contractor Submittals

Screening Plant Record Drawings

Drawings

Screening Plant Record Drawings	Title Page
Record Site Plan	
Site Restoration Details	
Site Restoration Details	

Irrigation System Layout May 6, 2005

Notes from April 12, 2004 Site Inspection - North	C-1
Notes from April 12, 2004 Site Inspection - South	

Record Electrical Site Plan E-1
Electrical Details E-2

Surface Drainage Improvements	D-1
Surface Drainage Improvements	D-1A

Parker Property - Mine Side of Highway 37

Soil, Boulder, and Haul Road Removal	D-1
Grading Plan	D-2
Erosion Control Details	

Septic System

House I Septic System	ا	L
House 2 Septic System	2	2
2003 Site Restoration Plan - North	.C-1 <i>A</i>	

2005 DIC RESIDIATION TIME	1 101 111	
2003 Site Restoration Plan -	South	.A

Screening Plant Restoration March 2003 (work to be completed in 2003)

Screening Plant Restoration March 2003 (work to be completed in 2003)	Title Page
2003 Site Restoration Plan - North	
2003 Site Restoration Plan - South	
2003 Site Restoration Plan Details	
2003 Site Restoration Plan Details	



2003 Site Restoration Plan Details	
Electrical Site Plan	E-1
Electrical Details	E-2
BINDER 2	
Screening Plant Asbestos Removal Project (Signed by Parkers on 05-16-	02)
Screening Plant Asbestos Removal Project	-
Site Restoration Plan - North	
Site Restoration Plan - South	C-15B
Site Restoration Plan Details	
Site Restoration Plan Details	
Rainy Creek Fishing Dock Details	
Rainy Creek Fishing Dock Details Revised per Agreement between Gover	
Owner	
Electrical Site Plan	E-1
Electrical Details	
Screening Plant Test Pit Sampling Plan	Sheet 1 of 2
Screening Plant Test Pit Sampling Plan	
7	
Interim Erosion Control Plan - North	C-11
Interim Erosion Control Plan - South	
Interim Erosion Control Plan Details	
Screening Plant - North Approximate Locations of Archeological Trench a	nd Pit
Excavations and Soil Removal Test Pits dated 10/9/00	
Screening Plant - South Approximate Locations of Archeological Trench a	nd Pit
Excavations and Soil Removal Test Pits dated 10/6/00	
, ,	
Screening Plant Asbestos Removal Project August 2000	
Screening Plant Asbestos Removal Project	Title Page
Existing Conditions Plan - North	
Existing Conditions Plan - South	
Erosion Control Plan - North	
Erosion Control Plan - South	
Demolition Plan - North	
Demolition Plan - South	
Final Grading Plan - North	
Final Grading Plan - South	
Test Pits and Air Monitoring Locations - North	
· · · · · · · · · · · · · · · · · · ·	
Test Pits and Air Monitoring Locations - South	
MARCOR Drawing Submittal Dismantling / Demolition	C-10



Table of Contents Parker Property Information

Dismantling / Demolition	Sheet 2 of 2
Earthwork/Excavation	Sheet 1 of 2
Earthwork/Excavation	Sheet 2 of 2
Erosion Control	
Erosion Control	Sheet 2 of 2
Temporary Facilities	Sheet 1 of 2
Temporary Facilities	



Libby, Montana
Asbestos Project
Property Information
for
Mel and Lerah Parker
Former Screening Plant
5000 Highway 37 N
Libby, Montana
BINDER 1 of 2

TARGET SHEET

EPA REGION VIII

SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1073565

SITE NAME:	LIBBY ASBESTOS
DOCUMENT DATE:	01/09/2007
•	
Due to one of the fo	DOCUMENT NOT SCANNED flowing reasons:
☐ PHOTOGRAPHS	
☐ 3-DIMENSIONAL	
OVERSIZED	
☑ AUDIO/VISUAL	
☐ PERMANENTLY	BOUND DOCUMENTS
☐ POOR LEGIBILIT	Y
□ OTHER	
☐ NOT AVAILABLE	
	MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DOCUMENT DESCR	IPTION:
DOCUMENTS A 5 CDs - PROPER	ECIAL COLLECTION 18070, RELEASABLE AS OF 10/16/2006 (RECORDED 11/17/2006) TY INFORMATION FOR MEL AND LERAH PARKER, ENING PLANT, 5000 HIGHWAY 37 N

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1073565

	DOO	OMENT NOMBER
	TE NAME:	LIBBY ASBESTOS 01/09/2007
Dι	ue to one of the foll	DOCUMENT NOT SCANNED owing reasons:
	PHOTOGRAPHS	
	3-DIMENSIONAL	
v	OVERSIZED	
	AUDIO/VISUAL	
	PERMANENTLY B	OUND DOCUMENTS
	POOR LEGIBILITY	•
	OTHER	
	NOT AVAILABLE	
		MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DC	OCUMENT DESCRI	PTION:
	SEE TABLE OF CO	ONTENTS (TOC)